

**Double-Mold Construction for CPC1125N  
PCN1032  
June 16, 2014**

## PCN1032 Double-Mold Construction for CPC1125N

June 16, 2014

To Our Valued Customers:

The following is to inform IXYS Integrated Circuits Division customers of an impending change to the CPC1125N Single-Pole, Normally Closed 4-Pin SOP OptoMOS Relay. As part of our commitment to continuous improvement of our processes and products, we occasionally make revisions to the construction and materials used in our parts. IXYS Integrated Circuits Division's quality system requires customer notification under the circumstances outlined below.

IXYS Integrated Circuits Division's notification policy states:

*IXYS Integrated Circuits Division is mindful that changes to process or product could have an adverse impact on our customers.*

*Therefore we verify, through our qualification methodology, that a change does not negatively affect product quality or reliability. We also verify that it does not impact form, fit, or function.*

*Changes to function are notified to the customer if the change could adversely affect the customer but not if the change is to enhance product performance beyond the current specification, for example, higher isolation voltage capability for Solid State Relays.*

*In cases where a planned change would impact form, fit, or would adversely affect function, quality or reliability, we notify the customer 90 days in advance.*

*We also notify our customers of planned product obsolescence.*

The following definitions apply:

*Form: the visual appearance including color, marking, and surface finish*

*Fit: the external dimensions and associated tolerances*

*Function: the electrical, mechanical, thermal, quality and reliability performance characteristics*

IXYS Integrated Circuits Division notifies customers of the changes using a Product Change Notification (PCN). Attached are the details of the pending product change.

Sincerely,

Steven Andreyk  
Director of Marketing

## **Part Change Notification**

---

The PCN number assigned to the change is **PCN1032** and should be referenced in any correspondence related to the change.

### **Products Affected**

CPC1125N

### **Detailed Description of Change**

IXYS Integrated Circuits Division will be changing the assembly of the device from an optical gel-based lightpath construction to a double-molded construction. The change will take effect immediately.

### **Reason for the Change**

The change will increase assembly automation, reduce product variability and increase the overall product quality.

### **Anticipated Impact on Quality and Reliability**

This change will have improved product quality. The maximum off-state leakage current specification limit will increase from 1uA to 5uA as reflected on the new data sheet DS-CPC1125N-R03.

### **Contact Information**

For any questions related to the PCN notice, please contact IXYS Integrated Circuits Division's Quality Assurance Department as indicated below:

Martha Brandt  
Quality Assurance Department  
IXYS Integrated Circuits Division  
78 Cherry Hill Dr.  
Beverly MA, 01915  
Phone: 978-524-6700